Bradbury Stamm: ABCWUA - Customer Service and Operations Facilities



Storm Water Compliance Inspection Form

PO Box 400 Los Lunas, NM 87042 www.greenglobenm.com

Inspection Type: Routine **Date:** 03-27-2020 **Time:** 2:05 PM

Permit Tracking #: NMR10025I Inspector Name: Mario Alderete Qualifications: Inspector

Current Weather Conditions: Date and Amount of Last Recordable Storm Event: 11-21-2019 1"

Construction Time Line:

Action	Start Date	Date Complete
Initial BMP Installation		
Clearing and Grubbing		
Utility Installation		
Construction of Structure		
Final Stabilization		

Site Walk:

Yes	No	N/A	Comment
\boxtimes			
\boxtimes			
\boxtimes			
	\boxtimes		Inlet protection needs to be cleaned up
		\boxtimes	
\boxtimes			
		\boxtimes	
	\boxtimes		
\boxtimes			
X			stockpiles are being activly used
		\boxtimes	Site looks good!

Bradbury Stamm

NMR100251

Date

Bradbury Stamm: ABCWUA - Customer Service and Operations Facilities

SWPPP Information:

	Question	Yes	NO	N/A	Comment
Is the SWPPP kep	t on site?	\boxtimes			
Was the SWPPP u inspection?	pdated at the time of the	\boxtimes			
Are all certification	pages signed?	\boxtimes			
Are inspector qual	ifications in the SWPPP?	\boxtimes			
Is there a copy of letter?	the NOI and Acknowledgement				
Is there a delegation	on letter in the SWPPP?	\boxtimes			
Was the last inspection/CAL certified?				\boxtimes	
personnel properly gath for gathering the inform	nered and evaluated the information subr	nitted. Bas le best of r	ed on my i ny knowle	inquiry of tl dge and be	direction or supervision in accordance with a system designed to assure that qualifie the person or persons who manage the system, or those persons directly responsible elief, true, accurate, and complete. I am aware that there are significant penalties for ations."
Name	Signature				Date
Operator: Eloy apoda	ca GUM	Λ <i>/</i>			04-04-2020

Name Additional Comments:

Signature

Bradbury Stamm: ABCWUA - Customer Service and Operations Facilities



Action Log:

Location	Action Type	Action Required	Date Noted	Date Completed	Initials
Inlet protection	Maintenance	Inlet protection needs to be cleaned up	04-03-2020		
Sweep street		Sweep street	03-20-2020		

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Inspector: Mario Alderete / 5/40 / 03-27-2020

Name Signature Date

Site Walk Deficiency Photos - Inlet protection