Bradbury Stamm: ABCWUA - Customer Service and Operations Facilities



Storm Water Compliance Inspection Form

PO Box 400 Los Lunas, NM 87042 www.greenglobenm.com

Inspection Type: Routine Date: 12-31-2019 Time: 4:44 PM

Permit Tracking #: NMR10025| Inspector Name: Carlos Flores Qualifications: CISEC

Current Weather Conditions: clear Date and Amount of Last Recordable Storm Event: 11-21-2019 1"

Construction Time Line:

Action	Start Date	Date Complete
Initial BMP Installation		
Clearing and Grubbing		
Utility Installation		
Construction of Structure		
Final Stabilization		

Site Walk:

Question	Yes	No	N/A	Comment
Is there a proper posting sign?	\boxtimes			
Are areas that have been disturbed, but not under construction been properly stabilized?			\boxtimes	
Velocity Reduction Devices i.e. Check Dams, Berms, Etc.			X	
Silt Fence	\boxtimes			
Wattles/Filter Sock	\boxtimes			
Inlet Protection	\boxtimes			
Cut Back Curbs			\boxtimes	
Waste Management	\boxtimes			
Vehicle Tracking Control	\boxtimes			new rock installed
Material Storage			\boxtimes	
Dust Control	\boxtimes			
Street Sweeping		\boxtimes		sweep street if needed for trackout
Construction Washouts i.e. Concrete, Paint, Stucco Etc.		\boxtimes		
Discharge Points	\boxtimes			
Sanitary Stations	\boxtimes			
Stockpiles	\boxtimes			stockpiles are being activly used
Other			\boxtimes	

Bradbury Stamm

Signature

NMR100251

Date

Bradbury Stamm: ABCWUA - Customer Service and Operations Facilities

SWPPP Information:

Question	Yes	No	N/A	Comment		
Is the SWPPP kept on site?	\boxtimes					
Was the SWPPP updated at the time of the inspection?						
Are all certification pages signed?	\boxtimes					
Are inspector qualifications in the SWPPP?	\boxtimes					
Is there a copy of the NOI and Acknowledgement letter?						
Is there a delegation letter in the SWPPP?	\boxtimes					
Was the last inspection/CAL certified?			\boxtimes			
"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualifie personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations." Owner: ABCWUA						
Name Signature				Date		
Operator: Floy anodaca						

Name **Additional Comments:**

Bradbury Stamm: ABCWUA - Customer Service and Operations Facilities



Action Log:

Location	Action Type	Action Required	Date Noted	Date Completed	Initials
Sweep street - Mission	Maintenance	Sweep street for sediment	11-12-2019		
Washout on ground - CWO Area	Maintenance	Clean and dispose of CWO from ground, Container leaks.	12-17-2019		

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Inspector:	Carlos Flores	12-31-2019	
-	Name	Signature	Date