CITY OF ALBUQUERQUE



August 7, 2020

David Soule, PE Rio Grande Engineering P.O. Box 93924 Albuquerque, NM 87199

Re: Jefferson Hotel

4949 Jefferson St. NE

Request for Certificate of Occupancy

Transportation Development Final Inspection

Engineer's/Architect's Stamp dated 9-10-18 (F17D044C)

Certification dated 7-28-20

Dear Mr. Soule

Based upon the information provided in your submittal received 7-28-20, Transportation Development cannot approve the release of Certificate of Occupancy for the above referenced project.

PO Box 1293

Prior to the issuance of a permanent Certificate of Occupancy, the following items must be addressed:

Albuquerque

- Please complete concrete for ADA access from sidewalk to public entrance of Building. (See Plan for locations)
- Please add ADA ramp (See Plan for location)
- Please complete asphalt parking.

NM 87103

 Please add truncated domes to wheelchair ramps located in the public right of way.

www.cabq.gov

Once corrections are complete resubmit

- 1. The approved and stamped TCL with changes drawn in red.
- 2. Transportation Certification letter on either the plan or applicants letterhead.
- 3. A Drainage Transportation Information Sheet (DTIS)
- Send an electronic copy of your submittal to PLNDRS@cabq.gov.
- 5. The \$75 re-submittal fee for log in and evaluation by Transportation.

If you have any questions, please contact me at (505) 924-3981.

CITY OF ALBUQUERQUE



Sincerely,

Ernie Gomez,

Plan Checker, Planning Dept. Development Review Services

EG

via: email

C:


CO Clerk, File

PO Box 1293

Albuquerque

NM 87103

www.cabq.gov



RIO GRANDE ENGINEERING OF NEW MEXICO, LLC

TRAFFIC CERTIFICATION

I, DAVID SOULE, NMPE, OF THE FIRM RIO GRANDE ENGINEERING, HEREBY CERTIFY THAT THIS PROJECT IS IN SUBSTANTIAL COMPLIANCE WITH AND IN ACCORDANCE WITH THE DESIGN INTENT OF THE APPROVED PLAN DATED 9/10/19. THE RECORD INFORMATION EDITED ONTO THE ORIGINAL DESIGN DOCUMENT HAS BEEN OBTAINED BY CHRISTOPHER MEDINA NMPLS 15702 OF THE FIRM TERRA LANDSURVEY CORPORATION. I FURTHER CERTIFY THAT I HAVE PERSONALLY VISITED THE PROJECT SITE ON 7/25/2020 AND HAVE DETERMINED BY VISUAL INSPECTION THAT THE SURVEY DATA PROVIDED IS REPRESENTATIVE OF ACTUAL SITE CONDITIONS AND IS TRUE AND CORRECT TO THE BEST OF MY KNOWLEDGE AND BELIEF. THIS CERTIFICATION IS SUBMITTED IN SUPPORT OF A REQUEST FOR CERTIFICATE OF OCCUPANCY.

EXCEPTIONS:

THE OWNER ELECTED NOT TO PAVE AL LARGE PORTION OF THE PARKING LOT, THE PARKING IS STILL WITHIN STANDARDS. THE DUMPSTER WAS MOVED DUE TO SOLID WASTE REQUEST.

THE RECORD INFORMATION PRESENTED HEREON IS NOT NECESSARILY COMPLETE AND INTENDED ONLY TO VERIFY SUBSTANTIAL COMPLIANCE OF THE TRAFFIC ASPECTS OF THIS PROJECT. THOSE RELYING ON THE RECORD DOCUMENT ARE ADVISED TO OBTAIN INDEPENDENT VERIFICATION OF ITS ACCURACY BEFORE USING IT FOR ANY OTHER PURPOSE.

ignature of Engin	eer or Architect
/28/20	OPEN METERS
ate	REGISTORESSIONAL TO 12.8 /
	POFESSIONAL