

# CITY OF ALBUQUERQUE



August 3, 2015

Jesse Trostle  
Nelson Morris  
3050 Pullman Street  
Costa Mesa, CA 92626  
jessyt@nelson-morris.com

**Re: Second Non-compliance for Concrete Wash-out and no Concrete Wash-out Station at Del Norte Dialysis Clinic; eNOI Tracking Number NMR12B711**

Dear Ms. Trostle,

On June 26th, 2015 you were informed of your NDPES CGP non-compliance due to a lack of a concrete washout station and concrete wash-out in numerous locations.

I visited the site today and the same non-compliance issues were present.

You have seven days to have a concrete wash-out station on site and to clean up the current concrete wash-out areas or your non-compliance will be reported to the New Mexico Environment Department, Surface Water Quality Bureau to aid in the determination if this issue is to be forwarded to the EPA.

If you have any questions, you can contact me at 924-3420.

Sincerely,

Curtis Cherne, P.E.  
Principal Engineer, Stormwater Quality  
Planning Dept.

C: email