



Date and Time of Inspection: 4-16-19 9:15/9:30
Project Name and Location: Lexus of Abingdon
Site Contact(s) and Company: Manny Rodriguez Jaynes Corp
COA Inspector Name: Curtis Cherne
ESC File No. and Owner NPDES ID NO.: F17E102, NMR 100217
Present Phase of Construction: grading
Type of Inspection: Regular During Storm Post storm 311/complaint Follow-up
Weather at time of Inspection: Clear Temp: 55
Estimated date of last storm that required an inspection: 3-15-19

Inspection Deficiencies:

City of Albuquerque Stormwater Inspector Signature and Date:

Ant C Chen
Signature

4-16-19
Date

Contact Info: Curtis Cherne, 505-924-3420, ccherne@cabq.gov

NUKE NOT MOVING until today, Env Health not fixed AT/