HYDROLOGY F18/D36 ONE PLAN

F18/D36

1 Plan

CITY OF ALBUQUERQUE DRAINAGE REPORT

ZONE ATLAS NO.	NAME OF CONSTRUCTION	OBSERVER	DATE OBSERVED
	Bill Kirk's Beach c	William Rogers	3 9 79

ADDRESS: [illegible]

Reason for Field Check: To the drainage report on the [illegible] ends

FINDINGS AND CONCLUSION: There is three footings over one on the north side of the ~~[illegible]~~ the other one on the south side of the everything look very good going by the plans.

FOLLOW UP ACTION REQUIRED: No follow-up will be needed because this ridge is paved.

SKETCH:

William R. Rogers
OBSERVER

James W. Miller AIA
Architecture
Planning

September 7, 1978

Engineering Division
City of Albuquerque
400 Marquette Avenue, NW
Albuquerque, New Mexico 87103

ATTENTION: Bruno

RE: Drainage Requirement - Bill King's Brake-O

Gentlemen:

I have talked with the agent for the owner of the property east of the above-referenced project. He has agreed to your request for a ditch on his west property line to facilitate drainage. The Owner's signature is included as per your request.

If you have any questions regarding this project, please do not hesitate to call me.

Sincerely,

Owner

Ben F. Shollenbarger

James W. Miller, AIA

Enclosure

3225-B Candelaria Rd. NE Albuquerque, New Mexico 87107
505 344-3639