HYDROLOGY F18/D37 ONE PLAN

F18- D37

1 PLAN

CITY OF ALBUQUERQUE DRAINAGE REPORT

ZONE ATLAS NO.	NAME OF CONSTRUCTION	OBSERVER	DATE OBSERVED
F-18	NW Day Care Bldg	William C. Rowe	3-20-79

ADDRESS: 5-8 Wilson Dr NE

Reason for Field Check: To the Drainage report on this New day care center.

FINDINGS AND CONCLUSION: Both the pondings area are required for this bldg one on the north side and the other one on the west side of the bldg. both pond back very good. This bldg. was approved for drainage by memo on 7-18-78

FOLLOW UP ACTION REQUIRED: No follow-up will be needed because this bldg is finish

SKETCH:

William C. Rowe
OBSERVER