HYDROLOGY TWO PLANS NO DOCUMENTS F18/D42

F18/D42

TWO PLANS

NO DOCUMENTS

G18/D28



THIS MICROIMAGE IS THE BEST POSSIBLE


POND
WATER POND
N
PARKING
WATER POND
BLDG STORE
FLOW

FIELD REPORT

PROJECT NO.	PROJECT DESCRIPTION	OBSERVER	DATE OBSERVED
	Motor Sport	William R. Peguero	9-20-78
~~OTHERS PRESENT~~:	6919 Montgomery N.E.		

Reason for Field Check: FOR THE DRAINAGE Report of THIS Motor Shop.

Description of Field Check Performed: THE PARKING lot is AT THE EAST SIDE OF THE BLDG. WITH THE flow GOING NORTH. AT THE END OF THE BLDG. THE IS A MANHOLE WERE All THE WATER DRAINAGE.

Findings or Conclusions: THE ONLY PROBLEM THAT I CAN SEE IS THAT THE ASPHAL HAS A FEW PLACES WERE THE WATER YES POND IN THERE. BUT OTHER THAN THAT, THERE IS NO PROBLEM.

Follow-up Action required: NO Follow-up will be needed because THIS BLDG. is FINISHED.

Submission Date of Field Report to: CITY: ALBUQUERQUE AMAFCA:

William R. Peguero
OBSERVER