

City of Albuquerque Stormwater Construction Site Inspection Report

General Information											
Project Name:		Champion Xpress									
Location:		4516 Wyoming Blvd									
Site Contact Name &		Jordan - 7Building & Dev.		ESC File No.	F20E005						
Agency		jordan@7bdev.com		NPDES Id. No.	NMR10028A						
Inspection Date:				350/1420hrs							
	water Inspector										
	ction Phase:	foundations Regular Storm Event Post Storm Event >0.25" 311/Complaint Follow Up									
Type of Ir	nspection: x	Regular	Storm Event	Post Storm I	vent >0.25"	311/Complaint	Follow Up				
Weathe	er at time of i	nspection?	Rai	n	Tempe	erature: ~	45*				
Estimated	date of last s	torm 0.25" o			Tempe		+5				
ltem											
			Deficien	cy/ Correctiv	e Action						
Number											
1	Please prevent trackout from entering the inlet on the NE corner of the site. This inles shoud be										
	protected. Installation of the trackout pad or persistant sediment removal in this area is another										
	option.										
2	Install addditional sediment BMP at the existing access points off of Wyoming.										
3	Please provide latest SWPPP self-inspection report.										
	······································										
2.1	Discharge off site?	(Y/N)	No								
4	Self Inspect	tion Reports	requested	Latest rep	oort Date:	not on	file				

Notes:			

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155