

## City of Albuquerque Stormwater Construction Site Inspection Report

				Genera	l In	formation				
Project Name:			Champion Xpress							
Location:			4516 Wyoming Blvd							
Site Contact Name &			Jordan - 7Building & Dev.			ESC File No.		F20E005		
Agency			jordan@7bdev.com			NPDES Id. No.		NMR10028A		
Inspection Date:				art/End Time:		20/1125hrs				
	water Inspe		r: Ti	mothy E. Sims	S					
	ction Phase:		foundations							
Type of Inspection:			Regular Storm Event			Post Storm Event >0.25" 311/Complaint x Follow U			x Follow Up	
Weath	er at time o	of i	nspection?	F	Rair	1	Tempe	rature: ~	30*	
Estimated	date of las	st s	torm 0.25" or	greater						
Item	Deficiency/Coursetive Astics									
Number	Deficiency/ Corrective Action									
1	Please prevent trackout from entering the inlet on the NE corner of the site. This inles shoud be									
T	protected. Installation of the trackout pad or persistant sediment removal in this area is another									
	option.									
<del>2</del>	Install addditional sediment BMP at the existing access points off of Wyoming.									
3	Please provide latest SWPPP self-inspection report.									
3	r lease prov	iuc	. Idlest SVVIII.	sen-mapeedio	1110	.port.				
2.1	Discharge off sit	e?	(Y/N)	No						
4	_		tion Reports	requested	d	Latest rer	ort Date:	not or	n file	
				1 0 9 0 0000		200001.0	70.12 410.			
Notes:										

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

02/04/20