



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	La Vida Llena				
Location:	10501 La Grima De Oro				
Site Contact Name & Agency	Oscar - Bradbury Stamm	ESC File No.	F21E028		
	orodriguez@bradburystamm.com	NPDES Id. No.	NMR1002G1		
Inspection Date:	04/21/20	Start/End Time:	0900/0930hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	earthwork and interior remodel				
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up

Weather at time of inspection?	Clear	Temperature: ~	62*
Estimated date of last storm 0.25" or greater	4/13/2020		

Item Number	Deficiency/ Corrective Action		
	no issues observed with this inspection		
	Please provide the latest SWPPP self-inspection report.		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date: not on file

Notes:	Site is currently testing for COVID-19. Inspection was completed from site perimeter maintaining a safe distance.

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 04/21/20