



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	La Vida Llena				
Location:	10501 La Grima De Oro				
Site Contact Name & Agency	Oscar - Bradbury Stamm	ESC File No.	F21E028		
	prodriguez@bradburystamm.com	NPDES Id. No.	NMR1002G1 & NMR1002PF		
Inspection Date:	06/09/20	Start/End Time:	1330/1400hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	earthwork and interior remodel				
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up

Weather at time of inspection?	Clear	Temperature: ~	69*
Estimated date of last storm 0.25" or greater	6/1/2020		

Item Number	Deficiency/ Corrective Action		
	no issues observed with this inspection		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 6/5/2020

Notes:	Site is currently testing for COVID-19. Inspection was completed from site perimeter maintaining a safe distance.

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 06/09/20