



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	La Vida Llena				
Location:	10501 La Grima De Oro				
Site Contact Name & Agency	Oscar - Bradbury Stamm	ESC File No.	F21E028		
	orodriguez@bradburystamm.com	NPDES Id. No.	NMR1002G1 & NMR1002PF		
Inspection Date:	08/06/20	Start/End Time:	0730/0740hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	earthwork and interior remodel				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Post Storm Event >0.25"	☐ 311/Complaint	☐ Follow Up

Weather at time of inspection?	Clear	Temperature: ~	70*
Estimated date of last storm 0.25" or greater	7/25/2020		

Item Number	Deficiency/ Corrective Action		
	no issues observed with this inspection		
	***Please forward the latest SWPPP self-inspection report.		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date: 6/5/2020

Notes:	Inspection was completed maintaining social distancing

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 08/06/20