

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Name:		Guardian Storage on Osuna					
Location:		4909 Juan Tabo Blvd NE					
Site Contact Name &		Paul Hedges-Guardina ESC File			F21E081		
Agency		pdhedges@h	otmail.com	NPDES Id. No.		NMR1002Q2	
Inspection Date:			art/End Time: 13	00/1330 hrs			
CoA Storm	water Inspecto	r: Ti	mothy E. Sims				
	ction Phase:			earth			
Type of Ir	rspection: x	Regular	Storm Event	Post Storm E	vent >0.25"	311/Complaint	Follow Up
Weath	<u>er at time of i</u>	nspection?	Clea	r	Tempe	rature: ~	85*
Estimated	ed date of last storm 0.25" or greater 6/1/2020						
Item	Deficiency/ Corrective Action						
Number	Deficiency/ Corrective Action						
Nullibei							
	no issues observed with this inspection						
	***Please provide latest SWPPP self-inspection report.						
	· · ·						
2.1	Discharge off site?	(Y/N)	No				
4	Self Inspec	tion Reports	requested	Latest rep	ort Date:	not on	file
	•	·			•		
Notes:							

 ${\bf City\ of\ Albuquerque\ Stormwater\ Inspector\ Signature\ and\ date:}$

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

06/18/20