

City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:		Guardian Storage on Osuna					
Location:		4909 Juan Tabo Blvd. NE					
Site Contact Name & Agency	Paul Hedges - pdhedges@hotmail.com		ESC File No.		F21E081		
	PDH Construction		NPDES Id. No.		NMR1002Q2		
Owner	Guardian Storage IV, LLC - Paul Hedges		Phone: (o)		505-450-6385		
Owner's e-mail	pdhedges@hotmail.com		Phone: (m)				
Inspection Date:	08/17/20	Start/End Time:	0730/0745				
CoA Stormwater Inspector:		Timothy E. Sims					
Construction Phase:		earthwork					
Type of Inspection:	Regular	Storm Event	Post Storm Event >0.25"	311/Complaint	x	Follow Up	

Weather at time of inspection?	Clear	Temperature: ~	71*
Estimated date of last storm 0.25" or greater	7/25/2020		

Item Number	Deficiency/ Corrective Action		
	no issues observed with this inspection		
	***Please forward the latest SWPPP self-inspection		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date: 8/1/2020

Notes:	inspection conducted adhering to Covid-19 constraints

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 08/17/20