

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No.	F21E	081 Project Name:			Guardian Storage		
NPDES Id. No. NMR10		0022Q Location:		4909 Juan Tabo Blvd. NE			
5/4/2021		Owner			Contractor		
Operator		Guardian Storage IV, LLC.					
Contact name & title		Paul Hedges			Dawson Hedges		
e-mail		pdhedges@hotmail.com			hedges72@comcast.net		
Contact Phone #		505-450-6385					
COA Inspector		Thomas Evans			Start/End Time: 2:05 PM/2:20 PM		
	tion Phase:	Building construction/flatwork					_
Type of Inspection:		Regular	Storm Event	Past Storm I	Event >0.25"	311/Complaint	Follow Up
Weather at time of i		nspection? clear			erature: ~ 72		
Estimated	date of last s	orm 0.25" or greater			5/3/2021		
Item							
Number	Deficiency/ Corrective Action						
1	Significant erosion in pond area at SW corner of site. Maintain erosion and sediment controls to						
	prevent any sediment from exiting the site. Remove sediment from the jogging path.						
2	Washout on the ground. Direct wash water from concrete, paint, and stucco into a leak-proof						
_	container per CGP 2.3.4. Remove and dispose of hardened concrete with other was						
	container per ear 2.3.4. Remove and dispose of hardened contrete with other waste per ear 2.2.3.						
3							
4							
5							
2.1	Discharge off site?	(Y/N)	no				
4	Self Inspec	tion Reports	Requested	Latest res	oort Date:	8/1/20	20
	'	•					
Notes:	Spoke with D	awson. Sel	f-inspection rer	orts are kept	electronicall	ly. SWPPP is at	the
office. Project is about 95% completed, with flatwork expected to be completed next week.							
J.110C. 110	Jeer is about	3370 COMPI	cca, with nath	J. R CAPCULC	. to be compi	CLCG HEAL WEEK	•

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Thomas Evans (505-803-6215)

tevans@cabq.gov

Thomas Evans 05/04/2021