

Date: 07/08/19

After Rain Event Construction Compliance Inspection For

Contractor: ABQ Development / Scott Patrick Homes

Site: Wilderness Canon

Conducted By: Jeff Hart

Time of visit: 14:00

Part 1: Walk through the facility and look for signs of erosion control measures that may have failed or been damaged from the recent rainfall event.

Table with 4 columns: Question, Y, N, Notes. Contains 4 rows of inspection questions regarding erosion control structures, ruts, mud, and BMP conditions.

Part 2: Inspection report summary.

Table with 2 columns: Question, Information/Comments. Contains 8 rows of summary questions including inspector name, qualifications, measures inspected, and rainfall data.

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature: [Handwritten Signature]

Printed Name: Jeff Hart

Date: 07/08/19

Title: Inspector

SWPPP Management Signature

[Handwritten Signature]

Date: 7/10/19