



# City of Albuquerque Stormwater Construction Site Inspection Report

## General Information

Project Name:	Saint Joseph on the Rio Grande		
Location:	5901 St Joseph		
Site Contact Name & Agency	James Orton - SDV <a href="mailto:jameso@sdvconstruction.com">jameso@sdvconstruction.com</a>	ESC File No.	G11E014A
Inspection Date:	06/12/19	Start/End Time:	1100/1130hrs
CoA Stormwater Inspector:	Timothy E. Sims		
Construction Phase:	vertical and interior work		
Type of Inspection:	<input type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25" <input checked="" type="checkbox"/> 311/Complaint <input checked="" type="checkbox"/> Follow Up

Weather at time of inspection?	Clear	Temperature: ~	82*
Estimated date of last storm 0.25" or greater	5/11/2019		

Item Number	Deficiency/ Corrective Action		
	no new issues observed and all previous issues resolved.		
1	Please provide a current (latest) SWPPP self-inspection report.		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date: 5/20/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:  
Contact information: Timothy E. Sims - (505) 803-6155  
[tsims@cabq.gov](mailto:tsims@cabq.gov) 06/12/19