



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Saint Joseph on the Rio Grande				
Location:	75901 St Joseph				
Site Contact Name & Agency	James Orton - SDV	ESC File No.	G11E014A		
	jameso@sdconstruction.co	NPDES Id. No.			
Inspection Date:	09/05/19	Start/End Time:	1100/1130hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	STABILIZED				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Post Storm Event >0.25"	☐ 311/Complaint	☐ Follow Up

Weather at time of inspection?	Clear	Temperature: ~	82*
Estimated date of last storm 0.25" or greater	7/7/2019		

Item Number	Deficiency/ Corrective Action		
	STABILIZED		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date:

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 09/05/19