

City of Albuquerque Stormwater Construction Site Inspection Report

General Information									
ESC File No.			oject Name:	Sequoia Apartments					
NPDES Id. No.	NMR1005BW		ocation:	5130 Sequoia Rd. NW					
3/3/2024		Owner			Contractor				
Operator		Nouri Apartments			J&S Development Inc.				
Contact name & title		Esmail Haidari			Jose Rodriguez				
e-mail		EsmailHaidari060@gmail.com			Rodriguez3003@hotmail.com				
Contact Phone #		505-250-6088			505-440-5104				
COA Inspector		Doug Hughes							
Construction Phase:		Slab and framing							
Type of Inspection:						Follow Up			
Weath	er at time of i	nspection?			Tempe	rature: ~	50		
Estimated date of last storm 0.25" or greater 5/4/2025									
Item Number	Deficiency/ Corrective Action								
4	The SWPPP and self-inspection reports were not available on-site during the inspection in Violation of CGP 7.3, City Ordinance § 14-5-2-11(C)(1), and CGP 4.7.3. No personnel were onsite, and the location of the SWPPP was not posted on a sign at the entrance. Required Mitigation: The SWPPP, including the SWPPP Map, Self Inspection Reports, and Corrective Action Reports, must be kept up-to-date per CGP 7.1 and available on-site per CGP 4.7.3, 5.4.3, and 7.3. If an on-site location is unavailable to keep the SWPPP when no personnel are present, notice of the plan's location must be posted near the main entrance of your construction site per CGP 7.3.								
2.1	Discharge off site?	(Y/N)	no						
4	Self Inspec	tion Reports	requested	Latest rep	oort Date:	?			

Notes:					
The SWPPP was not on site.					

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505) 924-3420

jhughes@cabq.gov

5/6/25 James D. Hughes