

## City of Albuquerque Stormwater Construction Site Inspection Report

M E Subar										
General Information										
Project Nai	me:	Chick-fil-A								
Location:		4001 CoorsB								
Site Contact Name &		Art Glynn- Buffalo Const.		ESC File No.		G11E069C				
Agency			faloconstruction.com	NPDES Id. No.		NMR1002EH				
Inspection Date:				45/1030hrs						
	water Inspecto	r:	Timothy E. Sims							
Construction Phase:			earth work egular   Storm Event   Post Storm Event >0.25"   311/Complaint							
Type of Ir	nspection: <u>x</u>	Regular	Storm Event	Post Storm E	event >0.25"	311/Complaint	Follow Up			
Weath	er at time of i	nspection?	Clou	dy	Tempe	rature: ~	48*			
Estimated	date of last s	torm 0.25" (	or greater		•	10/4/2019				
Item										
	Deficiency/ Corrective Action									
Number										
1	Silt fence on east and south sides require maintenance - from previous inspection.									
	***General Co	ontractor is co	onducting own SW	PPP self-inspe	ection reports	s. Kept on site in f	ield			
	book. Spoke with Art to start e-mailing me the reports.									
-										
							ł			
2.1	Discharge off site?	(Y/N)	No							
4	Self Inspect	tion Reports		Latest rep	oort Date:	10/17/2	019			

Notes:		

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155