City of Albuquerque Stormwater Construction Site Inspection Report

General Information									
Project Name:	Campbell Coumpound								
Location:	Campbell & KaylaLn NW - 2240 Campbell Rd								
Site Contact Name & Agency	T Scott Ashcraft			ESC File No.	G13E032				
	Adam Romero			NPDES Id. No.	NMR1001ZW				
Inspection Date:	11/18/19	Start/End Time:	0955/10/15hrs						
CoA Stormwater Inspector:		Timothy E. Sims							
Construction Phase:	STABILIZED								
Type of Inspection:	x	Regular		Storm Event		Post Storm Event >0.25"		311/Complaint		Follow Up

Weather at time of inspection?	Clear	Temperature: ~	52*
Estimated date of last storm 0.25" or greater	10/4/2019		

Item Number	Deficiency/ Corrective Action			
	STABILIZED			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports		Latest report Date:	

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov 11/18/19

Timothy E. Sims

Digitally signed by Timothy E. Sims
DN: cn=Timothy E. Sims, o=Stormwater Inspectionos, ou=Planning, email=tsims@cabq.gov, c=US
Date: 2019.11.19 10:23:37 -07'00'