

## City of Albuquerque Stormwater Construction Site Inspection Report

			General Info	rmation				
Project Name and Location		Bishop's Compound Rio Grande and Candelaria						
Site Contact Name & Agency		Scott Ashcraft Las Ventanas Homes			ESC File No. NPDES ID No.	G12E032		
Date of Inspection		11/01/18			Start/End Time	3:10pm 3:15pm		
COA Inspector Name		Cassandra Durkin, Stormwater Quality						
Describe Present Phase of Construction		Stabilized						
Type o	f Inspection:							
⊠ R	egular During stor	m event Pos	st-storm event (	> 0.25 inch)	311 / Complaint R	esponse Follow-Up		
			Weather Info	rmation				
Weath	er at time of this inspectio	n?			Ten	nperature: ~60 F°		
	Clear Cloudy I	Rain Sleet	□Fog □S	nowing [	Windy			
Has th	ere been a storm event sin		1.1	Yes No				
Amour	nt:	3''		]Snow "				
			Inspecti	on				
CGP	BMP / Activity	Maintenance Required? (1)	Corrective Action Required? (2)	Location and	l Notes			
1.5	Post a Notice							
2.2.1	Provide and maintain Natural buffer when Waters of the US < 50 ft							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.4	Minimize sediment track-out							
2.2.5	Manage stockpiles							

2.2.6	Minimize Dust			-				
2.2.10	Protect Storm Drain Inlets							
2.2.10	Protect Storm Drain Inlets							
2.2.11	Minimize erosion of conveyance channels							
2.2.12	Sediment Basins							
2.2.14	Stabilize exposed portions of the site.							
2.2.14	Stabilize exposed portions of the site.							
2.2.14	Stabilize exposed portions of the site.							
2.2.14	Stabilize exposed portions of the site.							
2.3.1	Equipment and Vehicle Fueling							
2.3.2	Equipment and Vehicle Washing							
2.3.3	Building Material Storage							
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage	c.						
2.3.3	Construction and Domestic Wastes							
2.3.3	Construction and Domestic Wastes							
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.							
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.							
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.							
2.4	Dewatering							
2.1	Discharge off site?		□Yes □No					
4	Self-Inspection Reports			Latest Report Date:				
	otes: (City Inspector Use) Items in compliance can be left blank.							

(1) Maintenance is to be complete by the end of the next business day.

(2) Corrective Actions are to be complete within 7 days.

Notes:		-	٦
	^	1	1
	4		_

11/01/18 Date

 $City\ of\ Albuquerque\ Stormwater\ Inspector\ Signature\ and\ Date:$ 

Contact Info: Cassandra Durkin, 505-924-983, cdurkin@cabq.gov