

City of Albuquerque Stormwater Construction Site Inspection Report

General Information						
Project Name:	Puerta Del Bosque					
Location:	Campbell & Rio Grande					
Site Contact Name &	Steve Hernandez - Sivage Community		nity ESC File No		G12E035	
Agency	steve@dmcnm.com		NPDES Id. No).	NMR10013N	
Inspection Date:	03/06/19	Start/End Time:	1100/1130hr	а		
CoA Stormwater Inspec	ector:		Timothy Si	Fimothy Sims, Stormwater Inspector		
Present Phase of	home construction					
Construction:						
Type of Inspection:	Regular	Storm Event	Post Storm	Event >0.25"	311/Complaint	x Follow Up
Weather at time of inspection?				Tempe	erature: ~	48*
	Clear					
Has there been a storm event since site was Permitted?						

Clarify amount: (i.e <1/4" to >3/4"):	Yes, >1/4"
--	------------

Inspection Maintenance or Corrective BMP / Activity **Location and Notes CGP** Action Section Required 1.5 please email me the NOI for this site for the file Post a Notice Provide and maintain Natural buffer when Waters of the US <50ft. 2.2.1 Sediment control along any perimeter 2.2.3 Sediment control along any perimeter 2.2.3 2.2.3 Sediment control along any perimeter 2.2.4 Minimize sediment track out

2.2.5	Manage stock piles			
2.2.6	minimize dust			
2.2.10	Protect storm drain inlets			
2.2.10	O Protect storm drain inlets			
2.2.11	Minimize erosion of conveyance channels			
2.2.12	Sediment Basins			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.3.1	Equipment and vehicle fueling			
2.3.2	Equipment and vehicle washing			
2.3.3	Building material storage			
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage			
2.3.3	Construction and domestic wastes			
2.3.3	Construction and domestic wastes			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.4	Dewatering			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports		Latest report Date:	2/27/2019
Notes: (City	Inspector Use) Items in compliance	ce can be left blank	· · · · · · · · · · · · · · · · · · ·	

Maintenance or corrective actions are to be completed within seven (7) days.

Notes:			
,			
	City of Albuquerque	Stormwater Inspector Signature and date:	
	Contact information:	Timothy Sims, 505-803-6155 or	03/06/19

tsims@cabq.gov

Construction General Permit (CGP)