



# City of Albuquerque Stormwater Construction Site Inspection Report

## General Information

Project Name:	Puerta Del Bosque				
Location:	Campbell & Rio Grande				
Site Contact Name & Agency	Steve Hernandez - Sivage	ESC File No.	G12E035		
	<a href="mailto:steve@dmcnm.com">steve@dmcnm.com</a>	NPDES Id. No.	NMR10013N		
Inspection Date:	06/10/19	Start/End Time:	1145/1200hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	Home construction				
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up

Weather at time of inspection?	Clear/ Windy	Temperature: ~	69*
Estimated date of last storm 0.25" or greater	5/11/2019		

Item Number	Deficiency/ Corrective Action		
1	Numerous washout on several lots - please mitigate		
2	Concrete washout facility requires maintenance and posting. Please post facility.		
3	Please provide latest SWPPP self-inspection report		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date:

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:  
Contact information: Timothy E. Sims - (505) 803-6155  
[tsims@cabq.gov](mailto:tsims@cabq.gov) 06/10/19