



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Puerta Del Bosque				
Location:	Campbell & Rio Grande				
Site Contact Name & Agency	Steve Hernandez - Sivage steve@dmcnm.com	ESC File No.	G12E035		
		NPDES Id. No.	NMR10013N		
Inspection Date:	07/31/19	Start/End Time:	1255/1300hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	Home construction				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Post Storm Event >0.25"	☐ 311/Complaint	☐ Follow Up

Weather at time of inspection?	Clear	Temperature: ~	91*
Estimated date of last storm 0.25" or greater	5/11/2019		

Item Number	Deficiency/ Corrective Action		
	no issues observed		
	Please provide latest SWPPP self-inspection report.		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date:

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 07/31/19