



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	G12E035	Project Name:	Puerta Del Bosque		
NPDES Id. No.	NMR10013N	Location:	Puerta Del Bosque Ln and Campbell Rd. NW		
5/12/2021	Owner	Contractor			
Operator	Sivage Community Development LLC				
Contact name & title	Steve Hernandez				
e-mail	steve@dmcnm.com				
Contact Phone #	505-228-1401				
COA Inspector	Thomas Evans		Start/End Time:	1:25 PM/1:35PM	
Construction Phase:	infrastructure/home construction				
Type of Inspection:	Regular	Storm Event	Past Storm Event >0.25"	311/Complaint Follow Up	
Weather at time of inspection?	clear		Temperature:	~ 75	
Estimated date of last storm 0.25" or greater	5/3/2021				
Item Number	Deficiency/ Corrective Action				
1	No posting of permit coverage. CLL sign is up, but the permit notice is not there.				
2	Hole in silt fence. Maintain silt fences to prevent soil from entering the street.				
3	Clean washout area. Remove and dispose of hardened concrete and other waste per CGP 2.2.3.				
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Requested	Latest report Date:	8/8/2020	

Notes:	No activity in the subdivision. Streets are clean

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Thomas Evans (505-803-6215)
tevans@cabq.gov

Thomas Evans 05/13/2021