



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Campbell Coumpound				
Location:	Campbell & KaylaLn NW - 2240 Campbell Rd				
Site Contact Name & Agency	T Scott Ashcraft	ESC File No.	G13E032		
	Adam Romero	NPDES Id. No.	NMR1001ZW		
Inspection Date:	07/01/19	Start/End Time:	0930/1000hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	Home Construction				
	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up

Weather at time of inspection?	Clear	Temperature: ~	79*
Estimated date of last storm 0.25" or greater	5/11/2019		

Item Number	Deficiency/ Corrective Action		
1	Washouts on various lots please clean and have trade utilize provided concrete washout facility.		
2	Please provide the latest SWPPP self-inspection report.		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	reports	Latest report Date: 5/10/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 07/01/19