



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Campbell Coumpound				
Location:	Campbell & KaylaLn NW - 2240 Campbell Rd				
Site Contact Name & Agency	T Scott Ashcraft	ESC File No.	G13E032		
	Adam Romero	NPDES Id. No.	NMR1001ZW		
Inspection Date:	08/21/19	Start/End Time:	1020/1030hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	Home Construction				
	☒ Regular	☐ Storm Event	☐ Post Storm Event >0.25"	☐ 311/Complaint	☐ Follow Up

Weather at time of inspection?	Clear	Temperature: ~	82*
Estimated date of last storm 0.25" or greater	7/7/2019		

Item Number	Deficiency/ Corrective Action		
	no issues observed with this inspection		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 8/20/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 08/21/19