

City of Albuquerque Stormwater Construction Site Inspection Report

| General Information | | | | | | | | | |
|----------------------|--|------------------------|-----------------|------------|----------------------------------|-------------------|-----------|--|--|
| ESC File No. | G14E097 | | Project Name: | | Calle Cuarta Apts. & TH WO | | | | |
| | NMR100631/NMR100632 | | Location: | | 3525 4th St NW | | | | |
| 2/13/2025 | | Owner | | Contractor | | | | | |
| Operator | | , , , | | | Pavilion Construction | | | | |
| Contact name & title | | -0 | | | Jared McCarn | | | | |
| e-mail | | pollice@yeshousing.org | | | jmccarn@pavilionconstruction.com | | | | |
| Contact Phone # | | 505-923-9607 | | | 505-668-8854 | | | | |
| COA Inspector | | Chancellor English | | | Start/End Time | | | | |
| Construction Phase: | | | | | , utilities for townhomes | | | | |
| Type of Inspection: | | Regular | Storm Event | Post Storm | Event >0.25" | 311/Complaint | Follow Up | | |
| Weath | er at time of i | nspection? | spection? Clear | | | Temperature: ~ 45 | | | |
| Estimated | Estimated date of last storm 0.25" or greater 11/7/2024 | | | | | | | | |
| ltem Number | Deficiency/ Corrective Action | | | | | | | | |
| 1 | BMPs - The perimeter silt fence on the north side along Fitzgerald Rd has collapsed in several sections and needs maintenance in violation of CGP Part 2.1.4. Required mitigation: Ensure all stormwater controls are maintained and remain in effective operating condition during permit coverage and are protected from activities that would reduce their effectiveness per CGP Part 2.1.4. | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| 2.1 | Discharge off site? | (Y/N) | no | | | | | | |
| 4 | Self Inspect | tion Reports | Yes | Latest re | port Date: | 2/3/20 |)25 | | |

| Notes: | | | | | |
|---|--|--|--|--|--|
| NMR1005D6 has been terminated. Replace NMR1005D6 with NMR100631 on the CGP Posting. | | | | | |
| Report is for both the apartment site and the townhouse site. | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

City of Albuquerque Stormwater Inspector Signature and date: 2/13/2025 Contact information: Chancellor English (505) 924-3325 cenglish@cabq.gov Chancel

Chancellor Inglish