# Back to Report List

## **INSPECTION REPORT**

**GENERAL INFORMATION** 

DATE OF INSPECTION: 12/29/2023 PERMITTEE NAME:

YES Housing, Inc. & Pavilion Construction, LLC **PROJECT NAME**:

Calle Cuarta

LOCATION:

3525 4th St. NW, Albuquerque, New Mexico, 87107

#### TRACKING NO:

NMR1005D6, NMR1005EN

COMPLIANCE EVALUATION:

## Satisfactory

**TYPE OF INSPECTION:** 

14Day

START TIME:

01:10 PM

END TIME:

01:30 PM

**INSPECTOR'S NAME:** 

Ryan Higdon

INSPECTOR'S TITLE:

Senior NPDES Inspector

INSPECTOR'S QUALIFICATIONS:

CISEC #2531

**INSPECTOR'S CONTACT:** 

505-867-4040

# PHASE OF CONSTRUCTION:

□ Clear and Grub Excavation Building (vertical)

🗌 Rough Grading 🗌 Infrastructure 🗌 Final Grading

Final Stabilization Suspension

## WEATHER INFORMATION



Snow and rain

#	STORM DATE	ESTIMATED STORM DURATION (HOURS)	APPROXIMATE PRECIPITATION (INCHES)
1	12/22/2023	4	0.16

#### WEATHER AT TIME OF THIS INSPECTION:

Clear

**TEMPERATURE**:

~ ~ ~ ~

<u>Help Terms Privacy</u>

© 2022 - <u>Comply26</u>

HAVE ANY DISCHARGES OCCURRED SINCE THE LAST INSPECTION?
Yes No ARE ANY DISCHARGES OCCURRING NOW?
Yes No ARE ANY PORTIONS OF YOUR SITE UNSAFE TO INSPECT?
Yes 💽 No

# **POLLUTION PREVENTION, SEDIMENT AND EROSION CONTROL BMP'S**

#	1
S&E/P2 CONTROLS	NPDES Permit Notification
MAINTENANCE	None
CORRECTIVE ACTION	None
LOCATION	7th St. Entrance
QUANTITY	1
UNIT	EA
рното	<u>Yes</u>
#	2
# S&E/P2 CONTROLS	2 Silt Fence
S&E/P2 CONTROLS	Silt Fence
S&E/P2 CONTROLS MAINTENANCE	Silt Fence None
S&E/P2 CONTROLS MAINTENANCE CORRECTIVE ACTION	Silt Fence None None
S&E/P2 CONTROLS MAINTENANCE CORRECTIVE ACTION LOCATION	Silt Fence None None Perimeter

# **GENERAL SITE INSPECTION ITEMS**

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
1	Is the SWPPP signage clearly posted with the correct information and properly displayed at an obvious perimeter location?	● Yes ● No ● N/A	🔵 Yes 💿 No	Posted
2	Are steep slope areas not actively being worked properly stabilized?	◯Yes ◯No ●N/A	Yes  No	

<u>Help Terms Privacy</u>

© 2022 - <u>Comply26</u>

Comply26

13 PM Comply26					
#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES	
3	Are disturbed areas not actively being worked properly stabilized?	● Yes ● No ● N/A	🔵 Yes 💿 No		
4	Are natural resource areas (e.g. streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	●Yes ●No ●N/A	🔵 Yes 💿 No		
5	Are discharge points and receiving waters free of any sediment deposits?	◯Yes ◯No ●N/A	🔵 Yes 💿 No		
6	Is trash/litter from work areas collected and placed in covered dumpsters?	● Yes ● No ● N/A	🔵 Yes 💿 No	Clean	
7	Are washout facilities (e.g. paint, stucco, concrete) available, clearly marked and maintained?	● Yes ● No ● N/A	🔵 Yes 💿 No		
8	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks or any other deleterious material?	● Yes ● No ● N/A	🔵 Yes 💿 No		
9	Are materials that are potential stormwater contaminants stored inside or in containers?	● Yes ● No ● N/A	Yes 💿 No		
10	Are offsite flows entering the construction site?	◯Yes ●No ◯N/A	🔵 Yes 💿 No	None	

11	Is there any evidence that pollutants are leaving the site or are not properly contained on site?	◯Yes ●No ◯N/A	🔵 Yes 💿 No	None observed during inspection
12	Are traffic and parking areas restricted so as to reduce soil erosion and dust?	● Yes ● No ● N/A	🔵 Yes 💿 No	

Comply26

3 P	VI		Comply26		
	#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
	13	Are non-stormwater discharges properly controlled?	● Yes  No  N/A	🔵 Yes 💿 No	
-	14	Is the project being operated in compliance with the SWPPP and with permit conditions at this time?	● Yes ◯ No ◯ N/A	🔵 Yes 💿 No	In compliance
	15	Are changes to the SWPPP necessary at this time?	◯Yes ●No ◯N/A	🔵 Yes 💿 No	
	16	Are dust control measures being properly implemented?	● Yes  No  N/A	🔵 Yes 💿 No	
	17	Are the SWPPP documentation and records up to date and accurately reflect the current conditions? (e.g. Site Map, Inspection Reports, Installation Dates)	● Yes ● No ● N/A	🔵 Yes 💿 No	Added new changes to swppp book

# **CERTIFICATION AND SIGNATURE BY INSPECTOR**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

## **INSPECTED BY:**

Ryan Higdon DATE: December 31, 2023 SIGNATURE AND AFFILIATION:

### CERTIFICATION AND SIGNATURE BY PERMITTEE

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

## PRINT NAME AND TITLE:

DATE:

SIGNATURE:

<u>Help</u> <u>Terms</u> <u>Privacy</u> © 2022 - Comply26

<u>Help Terms Privacy</u>

© 2022 - <u>Comply26</u>