

## City of Albuquerque Stormwater Construction Site Inspection Report

General information								
Project Nar	ne:	MJ Hospital	ity Self Storage					
Location:		1400 Yale						
Site Contact Name &			ARFA Const.	ESC File No.		G16E095F		
Agency		jasser007@	gmail.com	NPDES Id. No.		NMR1000YT		
Inspection Date:		09/11/19	Start/End Time: 12	220/1225hrs			•	
CoA Stormwater Inspector		r:	Timothy E. Sims	•				
Construction Phase:			•	vertical 2	2nd floor			
Type of Inspection: x		Regular	Storm Event	Post Storm E	vent >0.25"	311/Complaint	75* Follow Up	
Weather at time of inspection? Clear Temperature: ~ 85*								
<b>Estimated</b>	date of last s	torm 0.25" or greater			7/7/2019			
lhous								
Item	Deficiency/ Corrective Action							
Number								
	no issues obse	rved with th	is inspection, pleas	e provide me	the latest SW	/PPP self-inspection	on report	
			/					
					<del></del>			
2.1	Discharge off site?	(Y/N)	No					
	_			1 - 1 1		7/24/2	040	
4	Self Inspect	ion Report	s requested	Latest rep	ort Date:	7/24/2	019	
Notes:								

 $\hbox{City of Albuquerque Stormwater Inspector Signature and date:} \\$ 

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

09/11/19