

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	G17E		Project Name:		Raising Canes #852			
NPDES Id. No.	NMR1004EV		Location:		4800 Montgomery			
3/23/2023		Owner			Contractor			
Operator		Raising Cane's Restaraunts, LLC			MAPP, LLC - NMR1004MA			
Contact name & title		Robert Montgomery			Travis Nordie &			
e-mail		RMontgomery@raisingcanes.com			tnordie@mappbuilt.com			
Contact Phone #		806-786-0255			214-926-3117			
COA Inspector		Doug Hughes			Start/End Time: 2pm			
Construction Phase:					nplete			
Type of Inspection:		Regular	Storm Event		Event >0.25"	311/Complaint	Follow Up	
	er at time of i				Temperature: ~ 50			
Estimated	date of last s	torm 0.25" or greater 3/16/			3/16/2023	023		
Item								
Number	Deficiency/ Corrective Action							
1	Your site is stabilized. After all areas have been stabilized, you must contact your stormwater team for							
	verification that the "Final Stabilization Criteria" of CGP 2.2.14.c has been satisfied. This step is							
	independent of the Certificate of Occupancy (CO) process. Then satisfy the other "Conditions for							
	Terminating CGP Coverage" per CGP 8.2 including removal of BMPs. Next, file your "Notice of							
	Termination" (NOT) with the EPA. Please copy me with the documentation and the EPA's acceptance of							
<u> </u>	the NOT.							
2								
	Discharge off site?	(Y/N)	no					
	Self Inspec	tion Reports	required	Latest re	port Date:	non	e	
Notes:								

City of Albuquerque Stormwater Inspector Signature and date: 3 Contact information: Doug Hughes (505-924-3420) jhughes@cabq.gov Jan

3/23/23

James D. Hughes