



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	G19E004D	Project Name:	Albuquerque ER & Hospital
NPDES Id. No.	NMRI004HG	Location:	8220 Montgomery Blvd NE
6/13/2023	Owner	Contractor	
Operator	Nutex Health	Green Globe Environmental	
Contact name & title	James Thompson	Mathew Vallejos	
e-mail	JTHOMPSON@NUTEXHEALTH.COM	matt@greenglobenm.com	
Contact Phone #	713-805-0114	304-8473	
COA Inspector	Chancellor English	Start/End Time:	10am
Construction Phase:	CO Inspection		
Type of Inspection:	Regular	Storm Event	Post Storm Event >0.25"
		311/Complaint	Follow Up
Weather at time of inspection?	Clear	Temperature: ~	80
Estimated date of last storm 0.25" or greater	5/22/2023		

Item Number	Deficiency/ Corrective Action		
	None - CO Inspection		
	In accordance with City Ordinance § 14-5-2-11(C)(1), self-inspections must continue until the site is "determined as stabilized by the city." The property owner/operator is responsible for determining when the "Conditions for Terminating CGP Coverage" per CGP Part 8.2 are satisfied and then for filing their Notice of Termination (NOT) with the EPA. Each operator may terminate CGP coverage only if one or more of the conditions in Part 8.2.1, 8.2.2, or 8.2.3 has occurred. After filing the NOT with the EPA, the property owner is responsible for requesting a Determination of Stabilization from the City		
2.1	Discharge off site? (Y/N)	no	
4	Self Inspection Reports	no	Latest report Date:

Notes:	No inspections performed by COA prior to CO Inspection

City of Albuquerque Stormwater Inspector Signature and date: 6/27/2023
Contact information: Chancellor English (505) 924-3325
cenglish@cabq.gov

Chancellor English