

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
Project Name: La Mirada Townhomes								
Location:		Wyoming and La Mirada						
Site Contact Name &		James Seligman		ESC File No.		G19E038A		
Agency		Owner		NPDES Id. No.				
Inspection Date:			tart/End Time:	9:15	9:25		2000	
	water Inspector	r: (C	Curtis Cherne					
	tion Phase:			East units mostly complete				
Type of Inspection: Regular Storm Event Post Storm Event >0.25" 311/Complaint X Follow Up								
Weath	er at time of i	nspection?	Cle	ar	Temp	erature	70	
Estimated date of last storm 0.25" or greater 5/10/2019								
Item								
The last of the la	Deficiency/ Corrective Action							
Number								
1	numerous wash-out sin the dirt							
2	no acceptable wash-out facility on-site							
3 -	SWPPP self-inspection reports have not been submitted ac Report recid after writing this regard.							
	the state of the same of							
	Writing This Figure.							
					38)			
				-		-		
				-				
							-	
					· · · · · · · · · · · · · · · · · · ·			
			1					
2.1	Discharge off site?	(Y/N)	No			6-15-		
4	Self Inspect	tion Reports	_request	Latest rep	oort Date:	' '	-	
			•			-200		
Notes:								
. 10			- Cape o	(4.4)	10000	5.0		
			-10.0			LH-M-		
						7		
					26.29		203:00	
					-			
Ni.								

City of Albuquerque Stormwater Inspector Signature and date:

Contact information:

Curtis Cherne PE, 505-924-3420

ccherne@cabq.gov

06/18/19 Center a chem