

City of Albuquerque Stormwater Construction Site Inspection Report

			General	Information				
Project Na	ne:	La Mirada	Townhomes					
Location:		Wyoming and La Mirada						
Site Contact Name &		James Selig		ESC File No.		G19E038A		
А	gency	Owner		NPDES Id. No.				
Inspection Date:		06/21/19	Start/End Time:	9:00	9:10			
CoA Storm	water Inspecto		Curtis Cherne					
	tion Phase:			East units mo	stly complete			
	spection:	Regular	Storm Event	Post Storm E	vent >0.25"	311/Complaint	X Follow Up	
Weath	er at time of i	nspection	Cle	ar	Tempe	rature	75	
Estimated	date of last s	torm 0.25			5/10/2019			
in the latest and the								
Item			Deficier	ncy/ Correctiv	e Action			
Number								
	no issues							
	110 133003							
					75.7			
			-					
								
			1	1				
2.1	Discharge off site?	(Y/N)	No			A CONTRACTOR OF THE CONTRACTOR		
4	Self Inspec	tion Repor	ts	Latest rep	ort Date:	6/15/2	2019	
	· · ·	•		<u> </u>			0 N 10 20 A	
Alexan				*****				
Notes:								
	1020			HEEL .				
			100-100-		W-07			
2 4/								
		_		-				

City of Albuquerque Stormwater Inspector Signature and date:

Contact information:

Curtis Cherne PE, 505-924-3420

ccherne@cabq.gov

06/21/19 Cut a chem