



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Cannady Self Storage			
Location:	2100 Ladera Dr NW			
Site Contact Name & Agency	Devin Cannady devin@cannadystudio.com	ESC File No.	H09E001F	
		NPDES Id. No.	NMR1001lb	
Inspection Date:	03/18/19	Start/End Time:	09110/0930hrs	
CoA Stormwater Inspector:	Timothy Sims, Stormwater Inspector			
Present Phase of Construction:	verticle, metal building			
Type of Inspection:	<input type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input checked="" type="checkbox"/> 311/Complaint <input checked="" type="checkbox"/> Follow Up

Weather at time of inspection? Clear	Temperature: ~ 49*
---	--------------------

Has there been a storm event since site was Permitted?

Clarify amount: (i.e.. <1/4" to >3/4"):	yes, >1/4"
--	------------

Inspection

CGP Section	BMP / Activity	Maintenance or Corrective Action Required	Location and Notes
1.5	Post a Notice		
2.2.1	Provide and maintain Natural buffer when Waters of the US <50ft.		
2.2.3	Sediment control along any perimeter	x	SE corner of site dirt pile >50% of silt fence height
2.2.3			remove dirt pile to <50% - clean
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.4	Minimize sediment track out		

2.2.5	Manage stock piles		
2.2.6	minimize dust		
2.2.10	Protect storm drain inlets		
2.2.10	Protect storm drain inlets		
2.2.11	Minimize erosion of conveyance channels		
2.2.12	Sediment Basins		
2.2.14	Stabilize exposed portions of the site		
2.2.14	Stabilize exposed portions of the site		
2.2.14	Stabilize exposed portions of the site		
2.2.14	Stabilize exposed portions of the site		
2.3.1	Equipment and vehicle fueling		
2.3.2	Equipment and vehicle washing		
2.3.3	Building material storage		
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage		
2.3.3	Construction and domestic wastes	x	litter blown into site - please clean
2.3.3	Construction and domestic wastes	x	Header and J-trim plastic sheething - pick up
2.3.4	Washing applicators used for paint, stucco, concrete, etc.		
2.3.4	Washing applicators used for paint, stucco, concrete, etc.		
2.3.4	Washing applicators used for paint, stucco, concrete, etc.		
2.4	Dewatering		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date:

Notes: (City Inspector Use) Items in compliance can be left blank.

¹ Construction General Permit (CGP)

Maintenance or corrective actions are to be completed within seven (7) days.

Notes:	
please provide me with the latest self-inspection report.-	

City of Albuquerque Stormwater Inspector Signature and date: _____

Contact information: Timothy Sims, 505-803-6155 or tsims@cabq.gov 03/18/19