ECS File: HO9 BOITC1



TE SECOND				
	General Information			
Project Name and Location	Del webb smendy	Certer		
Site Contact Name & Agency	Del webb Amendy  Der webb    Cern Parton  Parte Hann	Contact Phone #	234-2057	
Date of Inspection	7-14-1 Start/End Time /0145/18:55			
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality			
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov			
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One			
Describe Present Phase of Construction	Stambzil			
Type of Inspection:				
Regular • During stor	rm event • Post-storm event (> 0.5 inch) • 3	311 / Complaint Resp	onse • Follow-Up	
	Weather Information			
Weather at time of this inspect		Tem	perature: ~F°	
Has there been a storm event s		Willdy		
Amount: • < 1/4" • 1/4" to 3		,		
	Erosion & Sediment Control Inspe	ction		
Entrance / Track-Out	NU			
Sediment Controls / Silt F     Check Dams, Waddles	, etc			
Erosion Controls / Mulch	, Seed, asphart, grand, tacks.	har m/ mula	<u> </u>	
Housekeeping/Pollutant C	Controls			
Debris/Pollutants/Sedime	nt in MS4			
• Notes				
Is site being maintained in complian	nce with the Drainage Ordinance ? $(Yes)$ No $S$	Curt C Le	7-1415 Date	

ECS File: 409 E017 C1



	General Information				
Project Name and Location	Del wolf Amity	asker			
Site Contact Name & Agency	Kings Custon	Contact Pho	one# 236-2657		
Date of Inspection	5~17~16 Start/End Time /():25				
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality				
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov				
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One				
Describe Present Phase of Construction	Constructs vertices and flat much				
Type of Inspection:	-	•			
Regular • During stor	rm event • Post-storm event (> 0.5 inch) •	311 / Complain	at Response • Follow-Up		
	Weather Information				
Weather at time of this inspect			Temperature: ~_6\int_F^\circ\$		
· Clear · Cloudy · 1		Windy			
Has there been a storm event s Amount: $\cdot < \frac{1}{4}$ " to $\frac{3}{4}$		,, 			
	Erosion & Sediment Control Insp	pection			
<ul> <li>Entrance / Track-Out</li> <li>Sediment Controls / Silt F</li> </ul>	•	few			
Check Dams, Waddles  Brosion Controls / Mulch	at In 1 1 hours	her & law	Sports		
<ul> <li>Housekeeping/Pollutant C</li> </ul>			V 1 -		
<ul> <li>Debris/Pollutants/Sedime</li> </ul>	nt in MS4 OIC				
• Notes					
Is site being maintained in complian	nce with the Drainage Ordinance ?* Yes No	Cut c Signature	S-17-11 Date		

## Cherne, Curtis

From:

Cherne, Curtis

Sent:

Tuesday, May 17, 2016 2:58 PM

To: Cc: Kevin Patton (Kevin.Patton@PulteGroup.com)

Subject:

michael@superiorstormwater.com Amenity Center SWPPP inspection

**Attachments:** 

missing\_fence.jpg

#### Kevin,

I wasn't planning on going to the Amenity Center, but when I was leaving the arroyo I noticed a section of silt fence was missing.

### Curtis

505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."

NPDES Tracking No: NMR12 109

ECS File: HODEON C 1



	General Information			
Project Name and Location	9100 Del wells			
Site Contact Name & Agency	Revin patter Contact Phone # 239-0746			
Date of Inspection	4-31-16 Start/End Time 12:25/12:40			
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality			
Inspector Phone / E-mail				
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One			
Describe Present Phase of Construction	Sin graded, contoh 67dy vertial, Flatwork			
Type of Inspection: Regular During stor				
	Rain · Sleet · Fog · Snowing · Windy  nce the site was Permitted? Yes · No			
	Erosion & Sediment Control Inspection			
<ul> <li>Entrance / Track-Out</li> <li>Sediment Controls / Silt F         Check Dams, Waddles,</li> </ul>	. 11			
<ul> <li>Erosion Controls / Mulch,</li> </ul>	Seed, NO			
<ul> <li>Housekeeping/Pollutant C</li> </ul>	ontrols $\partial \mathcal{U}$			
Debris/Pollutants/Sedimer	at in MS4			
· Notes Crurus will	be open in der 3 dan- speur to Milmio			
Fry for Tre	S justing - Tout tite every dissipate downster			
being maintained in compliance	ce with the Drainage Ordinance? Yes No Signature Date			



NPDES Tracking to .....

	General Information
Project Name and Location	General Information  Amenty Cuty  Merchaner Ptury 9/00 Rel wells  1 Corin Postfor Contact Phone # 239-0746
Site Contact Name & Agency	Public Hore!
Date of Inspection	4-12-16 Time 10:18/10-25
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One
Describe Present Phase of Construction	for grade!, bldy butional
Type of Inspection:  Regular • During sto	211 / Complaint Response • Follow-Up
	Weather Information  Temperature: ~_5\forall F
Has there been a storm event Amount: • < 1/4" • (74")	Erosion & Sediment Control Inspection
<ul> <li>Entrance / Off Tracking</li> <li>Sediment Controls / Silv</li> <li>Check Dams, Waddl</li> </ul>	
	ch, Seed,
	ment in MS4
	liance with the Drainage Ordinance? Yes (N) Cuto Che 4-13-4  Signature Date

ECS File: Ho9 Eurc)



	viole savidali mare pro-	1 Information		
	Genera	al Information	1	
Project Name and Location	General Del Marin Paffor	menty and		
Site Contact Name & Agency	Keris Patto	~		239-0746
Date of Inspection	2-1-16			11:15
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality			
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov			
Inspector Qualifications	Qualified Compliance I			A /
Describe Present Phase of Construction	bldg vohal	fix grade	1, walls.	fan ek
Type of Inspection:  • Regular • During sto	·		nplaint Response •	Follow-Up
	Weat	her Information		nperature: ~_31°F°
Has there been a storm event Amount: < 1/4"	since the site was Permitte	( )		
	Erosion & Sec			College College
Check any BMPs that I	nave FAILED or REQUI	RE MAINTENANCI	<u>E</u>	
Entrance / Off Tracking	-OF			
<ul> <li>Sediment Controls / Silt</li> <li>Check Dams, Waddle</li> </ul>				
Erosion Controls / Mulc	h, Seed,			
Wind Blown Erosion	~			
Debris/Pollutants/Sedin	nent in MS4			
•				/
Is site being maintained in compl	iance with the Drainage Ordin	nance? • (res. • No .	Cust c (	har 21-4 Date

NPDES Tracking No: NMR12 BA42

ECS File: 409 EOTIC1



	General Information				
Project Name and Location	Del wish knowly curter				
	9100 Del wolb				
Site Contact Name & Agency	1 Cerin Paston Andrio Tryillo - pluger	Contact Pho	one # 239 -0746		
Date of Inspection	Collection Start/End Time 2:15				
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality				
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov				
Inspector Qualifications	Qualified Compliance Inspector of Stormwate	er- Stormwater	One		
Describe Present Phase of Construction	Fin Groses bldg under a	mstructur			
Type of Inspection:					
• Regular • During sto	rm event • Post-storm event • 311 / Comp	olaint Respons	se • Follow-Up		
	Weather Information				
Weather at time of this inspect	ion?		Temperature: ~_35 F		
· Clear · Cloudy	Rain · Sleet · Fog · Snowing · V	Windy			
Has there been a storm events  Amount: • < 1/4" • 1/4" to					
	Erosion & Sediment Control Inspec	tion			
Check any BMPs that h	ave FAILED or REQUIRE MAINTENANCE				
Entrance / Off Tracking	entrane oz, min frack	out			
<ul> <li>Sediment Controls / Silt I Check Dams, Waddles</li> </ul>	0 - 1				
<ul> <li>Erosion Controls / Mulch</li> </ul>	, Seed, A				
• Wind Blown Erosion	<i>N</i> b				
<ul> <li>Housekeeping / Pollutant</li> <li>CNUS Autom</li> </ul>	Controls washis out in unline 1 billet of mid draps m	grund a	<i>\bigg\</i>		
Is site being maintained in complia	nce with Const. Gen. Permit ?* Yes No	gnature	Date		

## Cherne, Curtis

From:

Cherne, Curtis

Sent:

Friday, January 08, 2016 10:12 AM

To:

'antoniot@klingerllc.com'

Subject: Attachments:

Amenity Center SWPPP inspection washout-pit.jpg; bucket-washout.jpg

### Antonio,

I was out at the site on Wednesday and we just spoke on the phone.

I wanted to send a couple pics of the concrete wash-out.

If you could speak to the concrete/mortar subs, I'd appreciate it.

Thanks.

Curtis Cherne, P.E. Stormwater Quality

924-3420

NPDES Tracking No: NMR12BA42



## City of Albuquerque Stormwater Construction Site Inspection Report

ECS File: 409E017E1

	General Information				
	1- 1. L. Clarker Del with				
Project Name and Location	maior out of the				
	Mirchard Arroyo and willow Conyn Tre				
Site Contact Name & Agency	General Information  Annity Cluster Del with  Minhath Arroyo and willow Conyn Tol  Kerin potton Klinger  Contact Phone # 230-2857  Putter Homes  Start/End				
	Putte Hom J				
Date of Inspection	11-16-15 Start/End 16:30 /1/: A				
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality				
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov				
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One				
Describe Present Phase of Construction	rough greded				
Type of Inspection:					
Regular Uring stor	rm event • Post-storm event • 311 / Complaint Response • Follow-Up				
	Weather Information				
Weather at time of this inspect					
	Pain · Sleet · Fog · Snowing · Windy				
	ince the site was Permitted? • (Ye) • No  " • > 34" • Snow"				
	Erosion & Sediment Control Inspection				
Check any BMPs that ha	ave FAILED or REQUIRE MAINTENANCE				
■ Entrance / Off Tracking	9002				
<ul> <li>Sediment Controls / Silt F</li> <li>Check Dams, Waddles</li> </ul>					
* Erosion Controls / Mulch, Seed,					
• Wind Blown Erosion _	~~ ~ b				
<ul> <li>Housekeeping / Pollutant</li> </ul>	Controls 90v2				
Is site being maintained in complian	nce with Const. Gen. Permit ? Yes No Cut of 11-161				
	Signature Date				