



City of Albuquerque Stormwater Construction Site Inspection Report

Date and Time of Inspection: 4-15-19 9:50 - 10:45
Project Name and Location: Del Webb @ Mirehawn Ph 2
Site Contact(s) and Company: Dan Mallak, Kevin Patton, Paula Horner
COA Inspector Name: Curtis Cherne
ESC File No. and Owner NPDES ID NO.: H09E017F, NMR12AR19
Present Phase of Construction: vertical
Type of Inspection: Regular During Storm Post storm 311/complaint Follow-up
Weather at time of Inspection: cloudy Temp: 60
Estimated date of last storm that required an inspection: 3-12-19

Inspection Deficiencies:

- ① Lot - 1 Lot north of 2319 Woods wash:
: require sediment BMP, construction & domestic waste
- ② 2319 Woods wash - wash-out on lot
- ③ 2301 Woods wash - wash-out, domestic waste
- ④ 9136 Wind Caves - construction & domestic waste
- ⑤ 9208 Wind Caves - wash-out
- ⑥ 9212 Wind Caves - wash-out
- ⑦ 9220 - Wind Caves - wash-out
- ⑧ 2300 Kumatke - construction waste pile
- ⑨ 9236 Wind Caves - numerous wash-outs
- ⑩ 9252 Wind Caves - wash out slurry, construction and domestic waste
Sediment in street Wind Caves - 9236
- ⑪ 2305 Gold Butte - wash-out
- ⑫ 2308 Gold Butte - wash-out
- ⑬ 2316 Gold Butte - wash-out
- ⑭ 2331 Chuckwalla Spring - wash-out and construction waste
- ⑮ 2316 (across street) - construction waste
- ⑯ 2316 Chuckwalla Spring - construction waste backyard

City of Albuquerque Stormwater Inspector Signature and Date:

Curtis C. Cherne
Signature

4-15-19
Date

Contact Info: Curtis Cherne, 505-924-3420, ccherne@cabq.gov