NOTE: 2016 Protocol - Maximum of one SSWR per permit

PROPRIETARY COMPANY MATERIAL



Date & Time : <u>06-03-2021 at 3:24 PM</u>

NATIONAL STORM WATER QUALITY PROGRAM SITE INSPECTION REPORT (SIR)

For use on most PulteGroup Sites as of 01/01/2016

Commu	nity Name:	PulteGroup-MS-1026:	:Mirehaven, 9043 Fenton Lake F	Road NW, Albuquerque, NM 871	20 NPDES: NMR1000C1			
		(Include Site Name, Ci	ty, State, Zip Code and NPDES/	Construction Storm Water Perm	iit Number)			
Master Site List ID:		369	Inspection performed by: Mario Alderete, Inspector, Green Globe Environm					
				(Print N	ame, Company, and Title / Qual	ifications)		
Stages o	of Construction:	(check all that apply)	Land Development	Inactive	Vertical Construction	Post-Construction		
			Land and Vertical					
Type of Inspection:		(check all that apply)	Routine Inspection Other:	Storm-Event Related	Final Site Inspection			
I.	SWPPP - Respond	d to all Ouestions						
Item		(Yes	No		
A	Was the SWPPP accessible at the time of the inspection?					If "No," then an Action		
В		ly identified in the SWPPP?				Item is required.		
С	Does the SWPPP ref	lect the current stage of develor	oment?			Describe all Action Items		
D	Have all SIR action I	Items identified on the precedin	g reports been resolved?		百	on the reverse side of this sheet. (Section IV)		
E	Is NSQP Signage po	sted and in compliance with NS	SQP requirements?		$\overline{\boxtimes}$			
II.	Estimated date of	most recent Storm Event Th	at triggered an Inspection: <u>07</u>	<u>7-27-2020</u>				
	Provide rainfall info	rmation as required by the App	licable Permit: <u>.75 Inches</u>			e storm-event related Inspection required by the Applicable Permit)		
III.	Site BMP Inspecti	on	Not					
<u>Item</u>	SWPPP Items		<u>Applicable</u>	<u>Acceptable</u>	Action Item	Assigned To		
Erosion	Control							
1	Protection of Distur	bed Areas	\boxtimes					
2	Slope Protection			$\overline{\boxtimes}$				
3	Vegetation / Revege	tation	\boxtimes					
4	Velocity Reduction	Devices / Outlet Protection		\boxtimes				
Sedime	nt Control							
5	Check Dams (rock, g	gravel, other)		\boxtimes				
6	Silt Fence			\boxtimes				
7	Berms, Dikes, Straw	Wattles		\boxtimes				
8	Detention Basins/Se	ediment Traps		\boxtimes				
9	Stockpiles Protected	l/Stabilized			<u> </u>			
10	Storm Water Inlet Pr	otection		\boxtimes				
Housek	eeping / Trade Com	pliance						
11	Waste and Trash Mar	nagement		\boxtimes				
12	Spill and Leak Preve	ention						
13	Sanitary Stations			\boxtimes	<u> </u>			
14	Concrete and Constr	ruction Washouts						
15	Material Use and Po	tential Contaminate Storage		\boxtimes	<u> </u>			
16	Equipment Storage a			$ \boxtimes$	<u> </u>			
17	Construction Exits a	and Entrances		Ŭ	틸 -			
18	Dust Control				<u> </u>			
19	Street Sweeping			\bowtie	<u> </u>			

PROPRIETARY COMPANY MATERIAL

03-25-2021

Attach additional sheet(s) of SIR addendum if necessary

Corrective Action: Concrete washout needs to be cleaned up off the ground

Location and Responsive Action to be taken

Deficiency Name: Concrete washout lot

SWPPP Items (continued)

Site's Weathering of Storm Events

Non-Storm Water Flow

Site Discharge Points

Action Items

BMP Provider Performance

<u>Item</u>

21

22

23

IV.

Item

14

Other 20

SIR must be reviewed and signed below by SSWR - Not Delegable: I certify under penalty of law that Sections I-V of this document and all attachments were prepared by me or under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. In the event there are no Action Items in this report that have remained unresolved for a period in excess of that allowed by the Applicable Construction General Permit, I further certify under penalty of law that this Site is in compliance with the SWPPP and the Applicable Construction General Permit. I am aware that there are significant penalties for submitting false information including the possibility of fine and imprisonment for knowing violations. Certification applies to the area under the supervision of the SSWR signing this report.

Certified By: (SSWR - Must be a PulteGroup Employee)		Certified By: (Third Party Inspector if required by the Applicable Permit) Mario Alderete				
Site Storm Water Representative - Print Name and Title		Inspector - Print Name				
ite Storm Water Representative Signature (Use Ink)	Date	Inspector Signature (Use Ink)	Date			
Justification for non-completion of Responsive Actions						
Describe why any Responsive Actions were not corrected within the permit required time period (if applicable).						
		N/A				

Attach additional sheet(s) if necessary