

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No. H09E					McDonald's (30-0236)			
NPDES Id. No. NIVIR10			USLV Location: 1901 Ladera Dr NW		Ladera Dr NW			
1/25/2024		Owner		Contractor				
Operator		McDonald's USA LLC			Barnsly Construction			
Contact name & title		Shanta Rodriguez-Williams			Dan Barnsley			
e-mail		Shanta.Rodriguez@us.mcd.com		dan@barnsleyconstruction.com				
Contact Phone #		909-310-5886		505-264-0251				
COA Inspector		James Hughes		Start/End Tim	•			
Construction Phase:		Open for business - lar						
Type of Ir	spection:	Regular	Storm Event	Post Storm	Event >0.25"	311/Complaint Fo	ollow Up	
Weath	er at time of i	inspection?	Clea	r	Tempe	erature: ~	45	
Estimated date of last storm 0.25" or greater 1/4/2024						1/4/2024		
Item	ltem .							
Number	Deficiency/ Corrective Action							
	CAMPAD and self-ingression reports were unavailable an site in violation of City Online as \$ 44.5.2							
1	SWPPP and self-inspection reports were unavailable on-site in violation of City Ordinance § 14-5-2-							
	11(C)(1). The restaurant was open for business, and there were not any construction personnel onsite.							
	Required mitigation: Per City Ordinance § 14-5-2-11(C)(1), self-inspections must continue until the site							
	is "determined as stabilized by the city." The property owner/operator is responsible for determining							
	when the "Conditions for Terminating CGP Coverage" per CGP Part 8.2 are satisfied and then for filing							
	their Notice of Termination (NOT) with the EPA. Each operator may terminate CGP coverage only if one							
	or more of the conditions in Part 8.2.1, 8.2.2, or 8.2.3 have occurred. After filing the NOT with the EPA,							
	the property owner is responsible for requesting a Determination of Stabilization from the City. Email a copy of the latest self-inspection report to show compliance with the CGP and City Ordinance.							
	copy of the lat	test self-inspect	ion report to sho	w complianc	e with the CG	iP and City Ordinance.		
2	Posting The si	gn posting vour	NPDES Permit co	overage was	missing. Real	uired mitigation: You m	nust post	
_	Posting The sign posting your NPDES Permit coverage was missing. Required mitigation: You must post a sign or other notice of your permit coverage at a safe, publicly accessible location in close proximity to							
	the construction site. The notice must be located so it is visible from the public road that is nearest to							
	the active part of the construction site, and it must use a font large enough to be readily viewed from a							
	public right-of-way per CGP 1.5.							
3	Stabilization - landscaping still needs to be finished, and there is still about 700 square feet of bare dirt.							
	Required Miti	gation: Constru	ction isn't compl	ete until the	site is comple	etely stabilized		
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspec	tion Reports	missing	Latest rei	oort Date:	9/28/2023??	??	
<u> </u>		: : : : : : : : : : : : : : : : : : :				=, ==, = 3= 0	•	

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:

Doug Hughes (505-924-3420) Contact information:

jhughes@cabq.gov

1/26/24 James D. Hughes