



Receiving Waters and Critical Habitat: Rio Grande is located 3.6 miles to the NorhtEast.

Impairments: E. coli, Dissolved Oxygen, PCBs in Fish Tissue, Water Temperature

Grade: Before and After 1% to 2.5%