

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
Project Name:		Albuquerque RV & Boat Strorage						
Location:		2210 Vista Oriente NW						
Site Contact Name &		Dan Rich		ESC File No.		H10E006B		
Agency		emeraldprops@aol.com		NPDES Id. No.		NMR1000K2		
Inspection Date:		03/13/19 Start/End Time: 1230/1300hrs						
CoA Stormwater Inspect		tor:	Timothy Sims, Stormwater Inspector					
Present Phase of			verticle with some site work					
Construction:								
Type of Ir	spection:	Regular	Storm Event x	Post Storm	Event >0.25"	311/Complaint x	Follow Up	
	-							
Weath	er at time of i	•			Temper	ature: ~	51*	
		clear/Windy						
		orm event sin	ce site was Pe				1	
Clarify am	ount: ( i.e <1	/4" to >3/4"):			5, >3/4"			
				ection				
			Maintenance					
CGP	BMP /	Activity	or Corrective Action		Locatior	Location and Notes		
Section		. ,						
1.5	Post a Notice		Required					
1.5	Provide and maintain Na							
2.2.1	Waters of the US <50ft.							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3								
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.4	Minimize sediment track out							

2.2.5	Manage stock piles			
2.2.6	minimize dust			
2.2.10	Protect storm drain inlets			
2.2.10	Protect storm drain inlets			
2.2.11	Minimize erosion of conveyance channels			
2.2.12	Sediment Basins			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.3.1	Equipment and vehicle fueling			
2.3.2	Equipment and vehicle washing			
2.3.3	Building material storage			
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage			
2.3.3	Construction and domestic wastes			
2.3.3	Construction and domestic wastes			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.4	Dewatering			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports	requested	Latest report Date:	

Notes: (City Inspector Use) Items in compliance can be left blank.

<sup>1</sup> Construction General Permit (CGP)

Maintenance or corrective actions are to be completed within seven (7) days.

Notes:	03/12/19 a storm event exceeding 0.25" occurred. Please provide self-inspection report.
Provide s	elf inspection reports

City of Albuquerque Stormwater Inspector Signature and date:

Contact information:

on: Timothy Sims, 505-803-6155 or tsims@cabq.gov 03/13/19