

City of Albuquerque Stormwater Construction Site Inspection Report

General Information									
Project Name and Location		Albuqueque RV and Boat Storage 2201 Vistor Oriente Nu							
Site Contact Name & Agency		Joel Conant		ESC File No. NPDES ID No.	H10 E026B				
Date of Inspection		12-6-18		Start/End Time	30/2:50				
COA Inspector Name		Curtis Cherne, Stormwater Quality							
Describe Present Phase of Construction		Cunstruting souk and soncopuras							
Type of In	nspection: lar · During storm				ponse • Follow-Up				
Weather Information									
Weather at time of this inspection? • Clear Cloudy • Rain • Sleet • Fog • Snowing • Windy Temperature: ~ 45 F°									
Has there	been a storm event sin	ce the site was Pe	rmitted? Yes · No						
Amount:	• < 1/4" • 1/4" to 3/4"	' (> ³ / ₄ ')	• Snow"						
			Inspection						
CGP ¹ Section	BMP / Activity	Maintenance or Corrective Action Required	Location and Notes						
1.5	Post a Notice								
2.2.1	Provide and maintain Natural buffer when Waters of the US < 50 ft								
2.2.3	Sediment control along any perimeter		Southeast even	on street ?	rdine Bul				
2.2.3	Sediment control along any perimeter		dert in guster	- MMW					
2.2.3	Sediment control along any perimeter		, and the second						
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.4	Minimize sediment track- out								

2.2.5	Manage stockpiles		
2.2.6	Minimize Dust		
2.2.10	Protect Storm Drain Inlets		
2.2.10	Protect Storm Drain Inlets		
2.2.11	Minimize erosion of conveyance channels		
2.2.12	Sediment Basins		
2.2.14	Stabilize exposed portions of the site.		
2.2.14	Stabilize exposed portions of the site.		
2.2.14	Stabilize exposed portions of the site.		
2.2.14	Stabilize exposed portions of the site.		
2.3.1	Equipment and Vehicle Fueling		T .
2.3.2	Equipment and Vehicle Washing		
2.3.3	Building Material Storage		
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage	/	backets in lay-dum area
2.3.3	Construction and Domestic Wastes	V	trash souteat are , old car
2.3.3	Construction and Domestic Wastes	/	Dehric pile Southan
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.	V	trosh Soufrest and, old car Otheric pile South and wishout from arb cut
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.	/	norter wash-out, debris pile NW
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.	V	washing metal
-2.4	Dewatering		trash burnster has no over
2.1	Discharge off site?	· Yes (No)	
4	C ICT D		I dead Dead a Dedu

4 Self-Inspection Reports Latest Report Date:

Notes: (City Inspector Use) Items in compliance can be left blank.

Maintenance or corrective actions are to be completed within 7 days.

Notes:	JM CONANT @ GAAT	CL. (DM	 	
	□	d Calabana y Carana y		

City of Albuquerque Stormwater Inspector Signature and Date:

Centre Chre 12-6-18
Signature Date

Contact Info: Curtis Cherne, 505-924-3420, ccherne@cabq.gov

¹ Construction General Permit (CGP)