



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	H10E033	Project Name:	2200 Vista Oriente NW		
NPDES Id. No.	NMR10036M	Location:	2200 Vista Oriente NW		
4/20/2021	Owner	Contractor			
Operator	Tuan Huynh				
Contact name & title	Tuan Huynh				
e-mail	tuanvnhm@yahoo.com				
Contact Phone #	505-269-1418				
COA Inspector	Thomas Evans		Start/End Time:	1:30 PM/1:40 PM	
Construction Phase:	Pre-construction				
Type of Inspection:	Regular	Storm Event	Past Storm Event >0.25"	311/Complaint Follow Up	
Weather at time of inspection?	clear		Temperature: ~	68	
Estimated date of last storm 0.25" or greater	2/22/2021				
Item Number	Deficiency/ Corrective Action				
1	Remove and dispose of domestic waste				
2					
3					
4					
5					
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Requested	Latest report Date:		

Notes:	Site is stabilized with hydro-seed. Silt fence is in good condition.

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Thomas Evans (505-803-6215)
tevans@cabq.gov

Thomas Evans 04/23/2021