

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No. H10E		034 Project Name:			Cactus Patch Plaza		
NPDES Id. No. NMR10		00433 Location:			7801 La Morado Pl NW		
10/1	.7/2023	Owner	·		Contractor		
Operator		Pacific Cactus, LLC					
Contact name & title		Aaron Carlson					
e-mail		aaron.carlson@yahoo.com					
Contact Phone #		506-6310					
COA Inspector		Doug Hughes			Start/End Time:	2:45pm	
Construction Phase: Type of Inspection:		Land Regular Storm Event Past Storm			scaping Event >0.25"	311/Complaint Follow Up	
Estimated date of last storm 0.25" or greater 9/14/2023							
Item Number	Deficiency/ Corrective Action						
1	The NOI and permit coverage for this site expired February 17, 2022 and there was no submittal to continue permit coverage under the 2022 CGP, nor was there a Notice of Termination submitted. There is an estimated 1.1 acres of land disturbed without current CGP coverage in violation of CGP Part 1.4.3 and City Ordinance 14-5-2-11. Required mitigation: The operator of a site with 2017 CGP coverage were construction activities commenced prior to February 17, 2022 were required to submit a NOI no later than May 18, 2022 to continue permit coverage, as per CGP Part 1.4.3. The requirement for projects that disturb one acre or more must submit a current CGP NOI to the city is described in City Ordinance 14-5-2-11-(A).						
2	The permit coverage posting sign was on the ground and missing the NPDES ID and any contact information in violation of CGP Part 1.5. Required mitigation: You must post a sign or other notice of your permit coverage at a safe, publicly accessible location in close proximity to the construction site. The notice must be located so it is visible from the public road that is nearest to the active part of the construction site per CGP Part 1.5.						
3	The SWPPP and self-inspection reports were unavailable and no information providing the location was posted, in violation of CGP Parts 4.7.3, 5.4.3, and 7.3. Required mitigation: You must keep a current copy of your SWPPP (7.3), all inspection reports (4.7.3), and corrective action log (5.4.3) at the site or at an easily accessible location so that it can be made available at the time of an on-site inspection. If an on-site location is unavailable to keep the SWPPP when no personnel are present, notice of the plan's location must be posted near the main entrance of your construction site, according to CGP Part 7.3.						
	The stockpiles were neither covered nor stabilized in violation of CGP Part 2.2.5.c. Required mitigation: You must manage your stockpiles composed of sediment and/or soil by providing cover or appropriate temporary stabilization for piles that will be unused for 14 or more days per CGP Part 2.2.5.c.						
2.1	Discharge off site?	(Y/N)	no				
4		ion Reports		Latest rer	oort Date:	N/a	
<del>-</del>	Jen mapeet		Requested	Lucescie	Jore Dute.	T Y U	
Notes:	Notes: Provide latest self-inspection report.						
Earthwork getting close to 500 cy, G&D Plan required if more than 500 CY							
Earthwork getting close to 500 cy, G&D Plan required it more than 500 Cf							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Chancellor English (505-924-3325)

cenglish@cabq.gov