

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
SC File No.	H10E0	D6A6 Project Name:						
NPDES Id. No.			Location:	7411 La Morada Pl. NW				
	2/2021	Owner			Contractor			
Operator		United Concrete Co.						
Contact name & title		Isaac Rosas						
e-mail		joseisaac1983@gmail.com						
Contact Phone #		(505)290-1339						
COA Inspector		James Hughes			Start/End Time: 11:30 AM - noon			
Construction Phase:					onstruction			
Type of Inspection:		Follow-up	Storm Event			311/Complaint	Follow Up	
Weather at time of		nspection? clear			Temperature: ~ 42			
Estimated	date of last s	torm 0.25" or greater			10/1/2021			
Item								
	Deficiency/ Corrective Action							
Number								
	All areas of Concern have been mitgated. Permit coverage is posted, ESC Plan approved for Grading,							
	Sediment removed from street, and BMPs are inplace and in good condition.							
2								
3								
3								
4								
5								
6								
2.1	Discharge off site?	(Y/N)	Yes					
	*			<u> </u>		NI/A	N/A	
4	SW{PPP		missing	Latest report Date:		N/A	IN/A	
Matas	The site was	inactivo						
Notes: The site was inactive.								
Most of site was stabilized with AC millings.								
Edges and neighbors property still disturbed on 3 sides.								

City of Albuquerque Stormwater Inspector Signature and date: 12/23/2021

Contact information: James Hughes (505) 924-3942

Jhughes@cabq.gov

James D. Hughes