



# City of Albuquerque Stormwater Construction Site Inspection Report

General Information					
ESC File No.	H11E075		Project Name:	Playa del Sur	
NPDES Id. No.	NMR1006DO		Location:	5720 Miami Rd NW	
1/21/2025	Owner		Contractor		
Operator	Butterfly Holdings, LLC				
Contact name & title	Jarrod Likar				
e-mail	jarrodl@aswinc.com				
Contact Phone #	505-596-9037				
COA Inspector	Chancellor English		Start/End Time:	1pm	
Construction Phase:	Grading				
Type of Inspection:	Regular	Storm Event	Post Storm Event >0.25"	311/Complaint	Follow Up
Weather at time of inspection?	Clear		Temperature:	~ 30	
Estimated date of last storm 0.25" or greater			11/7/2024		
Item Number	Deficiency/ Corrective Action				
1	SWPPP - The SWPPP map does not reflect the current conditions of BMPs, materials storage, and sediment basins in violation of CGP Part 7.4.1. The self-inspection reports are not current in violation of CGP Part 4.7.3. Required mitigation: You must modify your SWPPP, including the site map(s), within seven days whenever you make changes to your construction plans, stormwater controls, or other activities at your site that are no longer accurately reflected in your SWPPP per CGP Part 7.4.1.a. You must keep a copy of all inspection reports at the site or at an easily accessible location, so that it can be made immediately available at the time of an on-site inspection per CGP Part 4.7.3.				
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Yes	Latest report Date:	12/4/2024	

Notes:	
The construction exit is full of sediment and needs maintenance/clean-out.	
Please send the most current self-inspection report.	

City of Albuquerque Stormwater Inspector Signature and date: 1/22/2025  
Contact information: Chancellor English (505) 924-3325  
[cenglish@cabq.gov](mailto:cenglish@cabq.gov)

*Chancellor English*