



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	H11E075	Project Name:	Playa del Sur		
NPDES Id. No.	NMR1006DO	Location:	5720 Miami Rd NW		
5/23/2025	Owner	Contractor			
Operator	Butterfly Holdings, LLC				
Contact name & title	Jarrood Likar				
e-mail	jarrodl@aswinc.com				
Contact Phone #	505-596-9037				
COA Inspector	Chancellor English	Start/End Time:	10:30am		
Construction Phase:	Grading				
Type of Inspection:	Regular	Storm Event	Post Storm Event >0.25"	311/Complaint	Follow Up
Weather at time of inspection?	Clear		Temperature: ~	78	
Estimated date of last storm 0.25" or greater			5/4/2025		
Item Number	Deficiency/ Corrective Action				
1	The self-inspection reports are not current in violation of CGP Part 4.7.3. Required mitigation: You must keep a copy of all inspection reports at the site or at an easily accessible location, so that it can be made immediately available at the time of an on-site inspection per CGP Part 4.7.3.				
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Yes	Latest report Date:	12/4/2024	

Notes:	
Please send the most current self-inspection report.	

City of Albuquerque Stormwater Inspector Signature and date: 5/27/2025
Contact information: Chancellor English (505) 924-3325
cenglish@cabq.gov

Chancellor English