

City of Albuquerque Stormwater Construction Site Inspection Report

	General Information			
Project Name and Location	Hacinda Don Villegas			
	Rio Grande L VIa Villegas			
Site Contact Name & Agency	Rio Grande L VIa Villegas Carlos lujer ESC File No. 1413 EDS 7 Road runner Real Estats			
Date of Inspection	Road runner Real Estats 2-12-18 Start/End Time /U:20/10:25			
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality			
Describe Present Phase of Construction	Stabilized			
Type of Inspection: Regular • During stor	rm event • Post-storm event (> 0.5 inch) • 311 / Complaint Response • Follow-Up			
	Weather Information			
Weather at time of this inspection of the control o	Temperature: ~ \(\frac{45}{5} \) F° Rain • Sleet • Fog • Snowing • Windy			
Has there been a storm event si Amount: • < 1/4" • (1/4" to 3				
	Erosion & Sediment Control Inspection			
Entrance / Track-Out				
Sediment Controls / Silt Fence, Inlet Protection, Wattles, etc.	5 3 461 11 42			
Inspection Reports				
Erosion Controls Housekeeping/Pollutant Contro	ols			
	V			
Debris/Pollutants/Sediment in Notes	MS4			
Is site being maintained in complian	ce with the Drainage Ordinance? Fee No Linto Chu 2-12-18 Signature Date			

ECS File: H13 EST



City of Albuquerque Stormwater Construction Site Inspection Report

000-000			
	General Information	S AFE	
Project Name and Location	Un Villeses 4 Ro Grando		
Site Contact Name & Agency	Contact Phone #/		
Date of Inspection	5-16-17 Start/End Time 10:20/10!	30	
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality		
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov		
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One		
Describe Present Phase of Construction	Stucco-ing house		
Type of Inspection:			
Regular • During stor	orm event • Post-storm event (> 0.5 inch) • 311 / Complaint Response • Follo	w-Up	
	Weather Information		
Weather at time of this inspect	Rain · Sleet · Fog · Snowing · Windy	<u>∫</u> F°	
Has there been a storm event s Amount: (< 1/4) 1/4" to 3			
	Erosion & Sediment Control Inspection		
 Entrance / Track-Out Sediment Controls / Silt F Check Dams, Waddles 	1 1 1 / N°		
 Erosion Controls / Mulch, 			
Housekeeping/Pollutant Controls Cenut polluhin - mixe not an top			
Debris/Pollutants/Sediments	ent in MS4		
Notes			
Is site being maintained in compliance with the Drainage Ordinance? Yes No Custo Char 5-16-17 Signature Date			

ECS File: M3 E053



City of Albuquerque Stormwater Construction Site Inspection Report

	General Information	
Project Name and Location	Haciente Don Villegas	
	Rio Grande and Mallhon	
Site Contact Name & Agency	Riv Grande and MeMben - Contos Copez Road Runger Real Botak UC Start/End Time 9:20/ 9:25	
Date of Inspection	12-22-16 Start/End 7:20/ 9:25	
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality	
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov	
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One	
Describe Present Phase of Construction	I house built, start built	
Type of Inspection: Regular During stor	rm event • Post-storm event (> 0.5 inch) • 311 / Complaint Response • Follow-Up	
	Weather Information	
Weather at time of this inspect • Clear • Cloudy •	Temperature: ~_5) F° Rain · Sleet · Fog · Snowing · Windy	
Has there been a storm event s		
Amount: • < 1/4" • 1/4" to 3/4" • > 3/4" • Snow"		
	Erosion & Sediment Control Inspection	
 Entrance / Track-Out Sediment Controls / Silt F Check Dams, Waddles 	etc. Inds un with	
Erosion Controls / Mulch, Seed,		
Housekeeping/Pollutant Controls		
Debris/Pollutants/Sedimes	nt in MS4	
· Notes drivenay has 2 grass stript 6" with the		
4 and	Sduk	
Is site being maintained in compliance with the Drainage Ordinance? Yes No Signature Date		